

SERVICE BULLETIN

NO. 230

DATE: 4/22/04



180 Kehoe Boulevard • P.O. Box 8770 • Carol Stream, IL • USA 60188
PH: 630.784.1000 • TF 877-392-7854 • FAX: 630.784.1655 www.ajantunes.com

TO: ALL AUTHORIZED SERVICE AGENTS IN NORTH AMERICA

SUBJECT: MOTORS FOR OUR CONTACT TOASTERS

Please remember that all **McDonald's Rapid Toasters, Models VCT-200 and VCT-250**, should now be using the **3 RPM Motor, part number 7000364**. This is a kit consisting of the motor, the mounting plate, associated hardware, a plastic bag, and finally the shipping carton. The motor itself has a number of 4000180.

The **9 RPM motor that is still used in the VCT-2000 toasters for Arby's and Burger King** has a part number of 7000240. Again this is a kit consisting of all of the above but the 9 RPM motor itself has a number on it of 4000167. This used to be used for McDonald's but should not be used in the McDonald's application as the motor was slowed down for their recent enhancement program.

At this time we are requesting to have these motors returned to us when they fail under warranty. This means the 9 RPM motor, P/N 7000240, and the 3 RPM used in the current McDonald's application should be returned to us along with the warranty claim. They fall just below the required minimum but we currently require them back for our own analysis. **THERE IS NO PROBLEM!!**

As always, thank you for your usual fine cooperation. If there are any questions about this or any other matter regarding our products or policies, please call the Tech Service Department at our toll free number, (877) 392-7854.