



A.J. ANTUNES & CO.

Phone: (630) 543-8650 ● Fax: (630) 543-0359 ● Web: www.ajantunes.com

April 27, 1999

TO:

FROM: John D. Pravdica

SUBJECT: SUPPLEMENT TO:
Service Bulletin SB113B dated 5/1/99
McDonald's Vertical Contact Toaster (VCT-200)
Conveyor Motor Replacement Kit (P/N 7000204)
Phase II

Service Bulletin SB113B covers replacing conveyor motors on all McDonald's VCT-200 toasters that were manufactured during the months of December 1998 and January 1999.

After mailing you this information, one of our dealers discovered that some additional toasters that they shipped fell into this update window. These toasters are listed on the attached supplement list.

In order to control costs, please try to coordinate the toasters on the attached supplement list with the toasters listed in SB113B.


We anticipate shipping you the additional conveyor motors, (P/N 7000204) to cover these additional sites during the week of May 10th, 1999.

If you have any questions, please give me a call.

Thank you for your usual cooperation.

Sincerely,

A. J. ANTUNES & CO.


John D. Pravdica
National Service Manager

JDP/drg



SERVICE BULLETIN INDEX

Page 1

NUMBER	DATE	TITLE
101	12-15-97	New Taco Bell TBS-1X and TBS-2X
102	02-01-98	Recall – Taco Bell Control Board, 407K002
103	03-01-98	Deluxe Food Warmers New Manual and Troubleshooting Tips
104	04-13-98	CCC-20 Corn Cooker
105	04-22-98	7000174 DCH Blower Bearing Kit
106	04-22-98	7000170 Check Valve Kits (DFW and HWD)
107	04-27-98	Taco Bell TBS-1X and TBS-2X (Specific Voltage Mfg. Nos.)
108	04-28-98	VCT-200 Owners Manual & Mandatory Spare Parts List
109	11-07-98	VCT-100 Hi-Limit Nuisance Shutdown
110	12-07-98	VCT-200 Platen T.J. Cinnamon 2 Year Warranty
111	12-10-99	Type K Thermocouple Check Charts
112	12-14-98	VCT-100/200 Front Tensioner (P/N 0011242)
113	12-15-98	VCT-200 Chain Guard and Wire Set Kits
113A	02-03-99	VCT-200 Chain Guard, Wire Set & Gear Motor Retrofit
113B	05-01-99	VCT-200, Gear Motor Retrofit, Phase II
114	01-11-99	VCT-200 Manual 1010710, Rev C
115	03-16-99	VCT-100/200 Conveyor Motor Gear Motors (P/N 7000175)
116	03-16-99	Serial Number I.D.
117	04-01-99	McDonald's Warranties and MT-12 Muffin Toaster Issues
118	05-10-99	McDonald's VCT Manual 1010710 Rev. D McDonald's VCT-100 Motor Warranty Update McDonald's VCT-100/200 Gear Reducer Lube Leakage
119	6-18-99	Roundup VCT-20 Deluxe Owners Manual (P/N 1010719) and Mandatory Stocking List

OVER

SERVICE BULLETIN INDEX

Page 2

120	6-22-99	Vertical Contact Toaster "Six Pack" Teflon Bearing Replacement Kit P/N 7000224
121	8-13-99	Service Replacement Kits for Water Solenoid Valves used on all Roundup Products
122	8-13-99	Roller Drive Chain Lubricant (P/N 2140146) used on all Vertical Toasters
123	8-13-99	McDonald's VCT-200 Conveyor Cover Update Kit (P/N 7000226)
124	8-13-99	New improved "Groovy Belt Wrap" used on all McDonald's Rapid Toasters (VCT-22/100/200) P/N 7000183