

SERVICE BULLETIN

NO. 193A

DATE: 8/07/03



180 Kehoe Boulevard • P.O. Box 8770 • Carol Stream, IL • USA 60188

PH: 630.784.1000 • TF 877-392-7854 • FAX: 630.784.1655 www.ajantunes.com

SUBJECT: REVISED VCT-200 VERTICAL CONTACT TOASTER REBUILD KITS

This is being revised because of the recent McDonald's TQK slow down program. The motor and its related parts have been removed and some prices have been changed. Please change your records accordingly.

#7000340	Rebuild Kit – Complete	List Price - \$405.60
		Suggested Install Time – 3 hrs.
Part Number	Description	Quantity In Kit for One Toaster
7000207	Conveyor Belt Chain Sprockets	8
7000224	Teflon Bearing Kit (6 Pack)	1
7000296	Ball Bearing Kit (2 Pack)	1
7000199	Spacer Kit (2 Pack)	1
7000248	Teflon Damper & Spring Kit	1
7000121	Slide Rail Kit (2 Pack)	2
0011264	Front (Heel) Conveyor Belt Chain	1
0011266	Rear (Crown) Conveyor Belt Chain	1
0011299	Idler Sprocket/Bearing Assembly	1
2150181	Drive Sprockets	2
2100259	Slide Bar Rails	4
2150117	Idler Shaft	2
2150118	Drive Shaft	2

#7000339	Rebuild Kit - Chain & Sprocket	List Price - \$241.80
	Area	Suggested Install Time - 1.75 hrs.
Part Number	Description	Quantity In Kit For One Toaster
7000207	Conveyor Belt Chain Sprockets	8
7000224	Teflon Bearing Kit (6 Pack)	1
7000296	Ball Bearing Kit (2 Pack)	1
7000199	Spacer Kit (2 Pack)	1
7000121	Slide Rail Kit (2 Pack)	2
0011264	Front (Heel) Conveyor Belt Chain	1
0011266	Rear (Crown) Conveyor Belt Chain	1
0011299	Idler Sprocket/Bearing Assembly	1
2100259	Slide Bar Rails	4

#7000338	Rebuild Kit – Drive Area	List Price - \$35.60
		Suggested Install Time – .75 hrs.
Part Number	Description	Quantity in Kit for One Toaster
7000296	Ball Bearing Kit (2 Pack)	1
*0011299	Idler Sprocket/Bearing Assembly	1
2150181	Drive Sprocket	2