

SERVICE BULLETIN

NO. 220

DATE: 11/6/03



180 Kehoe Boulevard • P.O. Box 8770 • Carol Stream, IL • USA 60188

PH: 630.784.1000 • TF 877-392-7854 • FAX: 630.784.1655 www.ajantunes.com

To: All U.S. Service Agencies

Subject: VS350 Variety Steamer Upgrade

We have initiated a few changes to our VS-350 Variety Steamers. The PRV valve has been removed from the bottom of the unit. It has been leaking when it is not cleaned which has become a nuisance to most restaurants. The #2170119 Valve is no longer available. It has been replaced by the #7000404 manifold kit. If you get a call on a leaking PRV valve, we will exchange the manifold kit for the PRV valve in Warranty no matter how old the steamer is.

We have also made changes to the Wire gauge and the High Limit. These are all available in kit Number #7000402. The Final change is a new relay along with a new heat sink. This replaces the #405K125 relay in the VS-350 units only!!

		<u>LIST PRICE</u>
#7000402	Wire & Hi-Limit Kit	\$81.20
#7000403	Relay Kit	\$71.50
#7000404	Manifold Kit	\$290.50

Attached is the new Operating Manual #1010745 Rev. D. VS-350's with these changes began shipping at the end of September.

We are working out a program to automatically rework all Smokey Bone's units as they are the major user. We will be notifying each service company with Smokey Bone's in their area in the next few weeks.

If you have any questions please contact Technical Service at 1-877-392-7854.