



A.J. Antunes & Co.

**SERVICE BULLETIN**

**No. 287**

**Date: 11-6-08**

---

**TO: Authorized Service Agents**

**SUBJECT: McDonalds UTX-200 Diagnostic Service Mode  
AJA Document #1011010.**

**AFFECTED ITEMS: McDonalds UTX-200**

**EXPIRATION DATE: NONE**

Please distribute this Service Bulletin #287 along with the Diagnostic procedure #1011010 to all of your technicians. The document #1011010 can also be found on our website. The Service mode is used to test all the functional areas of the toaster, one system at a time. It allows service personnel to take measurements and cycle the various systems. This should help the tech make a more accurate diagnosis of the problem and reduce the number of boards that are replaced and are not the real problem. This is not meant as a detailed troubleshooting guide. It should be used as a built in tool to track down the source of the problem. Other functions are available in the Service mode and are covered in other documents.

Regards:

Vince Kulik

Technical Team Manager / Trainer

877-392-7854

---

180 Kehoe Boulevard • P.O. Box 87700 • Carol Stream, Illinois 60188 USA

PH: 877-392-7854 • FAX: 630.784.1650 • [www.ajantunes.com](http://www.ajantunes.com)