

SERVICE BULLETIN

NO. 196

DATE: 1/7/03



180 Kehoe Boulevard • P.O. Box 8770 • Carol Stream, IL • USA 60188
PH: 630.784.1000 • TF 877-392-7854 • FAX: 630.784.1655 www.ajantunes.com

SUBJECT: MT-12 MUFFIN TOASTER – NEW INDICATOR LIGHTS, P/N 7000342

The Model MT-12 Muffin Toaster that A.J. Antunes & Co. manufactures for McDonald's Corporation has two Indicator Lights. These Lights have a bezel that under certain circumstances may come off. To address this possibility we have sourced out a new style Indicator Light that has a permanently secured bezel. We have also developed a Kit that includes both Lights, one 6 volt amber (partial load) & one 2 volt green (cycle completion), along with the simple instructions to replace them. The part number of this Kit is 7000342, and it has a list price of \$12.60.

This kit will take the place of both former Indicator Lights, part numbers 4060327 and 4060329. Please check your inventory for these two part numbers, document the quantities for each part number, and then remove these from your stock and discard them. Once you have the number of "old indicator lights" documented, you should then contact Lucy Witcher in our Technical Service Department at lucy.witcher@ajanatunes.com and report both quantities along with its corresponding part number and description. If you'd like, you may fax Lucy at (630) 784-1655. The appropriate number of Kits will then be sent to you at our expense.

MT-12 Muffin Toasters that are under warranty and require service for any one of the Indicator Lights should have both Lights replaced by using this new Kit, P/N 7000342. End users having Toasters not under warranty that are asking for one Light will need to be told about the Kit so they will know they'll be getting both Lights.

Please share this with everyone else in your organization you think warrants it and make the proper notation in your records.