

SERVICE BULLETIN

NO. 254

DATE: 11/22/05



A.J. Antunes & Co.

180 Kehoe Boulevard • P.O. Box 8770 • Carol Stream, IL • USA 60188

PH: 630.784.1000 • TF 877-392-7854 • FAX: 630.784.1655 www.ajantunes.com

TO ALL US AUTHORIZED SERVICE AGENCIES

SUBJECT: MT-12 Chip Upgrade

As stated in Service Bulletin #252, dated 11/9/05, McDonald's is upgrading the chip on the control board used in their "MT-12" Muffin Toaster. All new MT-12 toasters manufactured by A. J. Antunes will have the new board with the latest software chip installed when they are assembled at the factory. In order to ensure that all boards in your **current inventory** will have the latest chip installed for future repairs. We are asking you to upgrade these boards, P/N 407K010, with the latest software chip. In order to do this, we will send you the new software chip kit (P/N 7000663) at no expense to you. Then we are asking that you install the new software chip which will upgrade these Control Boards.

Therefore, we are requesting a complete count of the Control Boards, P/N 407K010, that you currently have in your inventory. It is important that we upgrade all current inventory of MT-12 Control Boards immediately.

***If none, please see last paragraph only.**

If you have one or more boards, please fax to us at 1-630-784-1650 a regular purchase order detailing the quantity of chip kits, **P/N/ 7000663**, that will be required to upgrade **Control Board #407K010** **"IN YOUR INVENTORY"**.

A.J. Antunes will process & ship this order free of any charges. Once you have received these chip kits, please proceed to install them on control board, P/N 407K010.

***When it is time to re-order control boards for your inventory, please order the new Control Board #7000664 which will contain the latest version of the chip. Control Board #407K010 has been discontinued.**